

DIGITAL SOFTWARE NEWS

FOR THE

PDP-8 & PDP-12

Software Information Service
Digital Equipment Corporation
Maynard, Massachusetts 01754

DIGITAL SOFTWARE NEWS
FOR THE PDP-8 AND THE PDP-12

Digital Software News for the PDP-8 & PDP-12 is designed to provide users of PDP-8 and PDP-12 software with up to date information on software problems, programming notes, and new and revised software. Each article, other than announcements and documentation corrections, is coded sequentially by system program in the lower right corner for ease in maintaining a quick reference file. The original material for such a file is supplied in the Software Performance Summary for the PDP-8 & PDP-12. This publication which is placed in each basic software kit, is a collection of all current information on known software problems, patches, and programming notes. As new versions correct software problems and obsolete patches, and reprinted manuals include programming notes and manual corrections, new articles in the Digital Software News will announce the revised software and specify by code which article should be removed from your Software Performance Summary file. Articles may also be replaced when new information becomes available; such as, procedure to circumvent a problem may replace the original report of the problem. All articles in the Digital Software News which should be added to your file will be appropriately coded.

Any questions or problems on the articles contained in these publications or concerning the use of Digital's software should be reported to the Software Specialist or Sales Engineer at your nearest Digital Office.

Additional copies of the current Software Performance Summary and updated issues of the PDP-8 and PDP-12 software price lists are available at no charge upon request from the Program Library. As with usual orders for software, the Program Library will accept orders received directly from U.S. customers. All other customer orders must be routed through the nearest Digital Representative.

PDP-8 & PDP-12 SOFTWARE NEWS

JUNE 1972

TABLE OF CONTENTS

OS/8 BUILD (DEC-S8-OBLDA-A) Programming note on configuring OS/8 systems	OS/8-BUILD	1
OS/8 Programming note for LS8E line printer handler	OS/8 LINE PRINTER HANDLER	1
PS/8 AND OS/8 SYMBOLIC EDITOR Patch to correct timing problem	OS/8 EDIT	4
OS/8 Programming note on use with TD8E DEctape	OS/8 TD8E	1
PDP-8/12 RTPS FORTRAN IV Programming note, formatted end of file	FORTRAN	6
PDP-8/12 RTPS FORTRAN IV Programming note, constants in call list	FORTRAN	7
RTPS FORTRAN IV MANUAL (DEC-08-LRTPA-A-D) (F4.SV version 1.06) Arithmetic statement function definitions	FORTRAN	8
RTPS FORTRAN IV (F4.SV version 1.06, RALF.SV version 51) The BLOCK DATA statement	FORTRAN	9
PDP-8/12 RTPS FORTRAN IV Problem with expression in I/O statement	FORTRAN	10
RTPS FORTRAN IV (F4SV version 1.06) Problem with logical expressions	FORTRAN	11
FOCAL-8 and FOCAL '69 Problem with M Command	FOCAL	19

TABLE OF CONTENTS (continued)

FOCAL-8	
Patch to correct Altmode location	FOCAL 18
TC58 IT PART 1 (MAINDEC-08-D9DE)	
Patch to correct short stall loops	MAINDEC 11
PDP-8/12 NEW AND REVISED SOFTWARE	
KE-8E (EAE) Instruction Test 2 multiply and divide MAINDEC-8E-DØMA	MAINDEC 12

Programming Note for LS8E line printer handler

The LS8E line printer is currently being sold with OS/8 configurations. The device handler for the LS8E is quite similar to the LE8 (LPØ8) handler, but there are enough differences between the printers such that the current LPØ8 handler will not work properly when used with the LS8E. There are two possible courses of action to take if the LS8E line printer is to be used as the system line printer:

- I) A new BUILD format LS8E handler has been generated and will be distributed with LS8E printers. This handler can be used with OS/8 BUILD to insert the handler into the system.
- II) For installations without paper tape readers, the standard line printer handler supplied with BUILD can be modified to drive the LS8E. The ALTER command available in BUILD should be used to do this. To change the standard line printer handler for LS8E, run BUILD, and enter the following:

\$ ALTER LPØ8,100 = 1371

\$ ALTER LPØ8,157 = 724Ø

\$ ALTER LPØ8,161 = 76ØØ

\$ ALTER LPØ8,164 = 7762

\$ ALTER LPØ8,171 = 6

These instructions alter the standard handler to drive the LS8E. Continue the BUILD procedure as needed, and terminate with

\$BOOT

when the

SYSTEM BUILT

message occurs, the LS8E handler is on the system with the name LPT.

OS/8 BUILD (DEC-S8-OBLDA-A)

Programming note on configuring OS/8 systems

With the release of OS/8, a new system configurator program, BUILD, has been introduced. BUILD allows the user to efficiently alter his peripheral devices quickly and easily. BUILD can also generate a system using the OS/8 and CD binary paper tapes. CONFIG.Ø5 is also distributed and can still be used to configure systems. Any of the procedures that could be used to build PS/8 systems can be used with OS/8. In addition, CONFIG.Ø5 has several additional parameters:

- TD8E: Setting TD8E = 1 will cause handlers for TD8E DECTape drives Ø&l to be used rather than TCØ8 DECTape. The units are non-system drives.
- TD8ESYS: Setting TD8ESYS - 1 will cause an assembly for the TD8E (12K core) as the system device. Unit Ø is the system device, unit 1 is resident at location 7614.
- ROM: For the 8K-ROM version of TD8E, set ROM = 1. Note that the ROM hardware must be present to use this option. If not, the user must have minimum 12K of core.
- RKØ1: The RK8 disk can be used as a non-system device by setting RKØ1 = n, where n is the number of drives available. The RK8 handlers will replace DECTape drives starting with DTA7. Thus, setting RKØ1 = 2 at assembly time will assemble handlers for RKAØ and RKA1, and will delete devices DTA7 and DTA6.

Thus, CONFIG, as well as BUILD provides facilities for creating OS/8 systems. Any new peripherals, however, will be distributed in BUILD format, or as modifications to BUILD itself. No major expansions of CONFIG are planned at this time.

PS/8 AND OS/8 SYMBOLIC EDITOR

Patch to correct timing problem

Both the PS/8 and OS/8 Symbolic Editor program (EDIT) exhibit timing problems when running on certain PDP-8/E's. Since some 8/E's are faster than others, the . = and / = commands will only print 3 digits of line number. The following corrects this problem.

PS/8 Editor

. GET SYS EDIT

. ODT

1226/6041 6046

1227/5226 6041

1230/6046 5227

7600G

. SAVE SYS EDIT

.

OS/8 Editor

. GET SYS EDIT

. ODT

1222/6041 6046

1223/5222 6041

1224/6046 5223

7600G

. SAVE SYS EDIT

.

OS/8

Programming Note on use with TD8E DECTape

The following information applies only to TD8E configurations, either 8K with MR8E Read-Only-Memory or 12K.

1) Making OS/8 system backup tapes.

Users should create a backup system tape immediately on receipt of the DECTape. The backup should be made before initializing the DECTape. Currently, no TD8E tape copy routine is being distributed. However, such a program will become a standard part of the TD8E kit. Meanwhile, a backup can be made by using the TD8E subroutine which is supplied as a standard tape in the kit. The procedure to follow to make a backup OS/8 system follows:

1. Using the Binary Loader, load the TD8E subroutine (DEC-8E-UZTA=PB) into core in field 0.
2. Mount the unused OS/8 system tape (DEC-S8-OSYSA-A-UC) on unit 0, WRITE LOCKED with the switch in the REMOTE position.
3. Mount a certified DECTape on unit 1, WRITE ENABLED, with the switch set to REMOTE.

Note: Be sure to wind a fair amount of tape onto the righthand reel of both units to get past the end zone region.

4. Toggle the following program into core in field 0:
(see following page)

/SIMPLE TD8E COPY PROGRAM

```

00200 0200 *200
00200 3205 DCA REC1 /START AT TAPE BLOCK 0
00201 3212 DCA REC2
00202 4632 LOOP, JMS I K7200 /READ OS/8 TAPE
00203 3610 3610
00204 0000 0
00205 0000 REC1, 0 /USES FIELD 1 AS BUFFER
00206 7402 HLT /INPUT ERROR
00207 4633 JMS I K7204 /WRITE COPY
00210 7610 7610
00211 0000 0
00212 0000 REC2, 0
00213 7402 HLT /THAT'S A WRITE ERROR! NEVER HAPPEN
00214 1205 TAD REC1
00215 1230 TAD K36 /UPDATE BLOCK TO COPY
00216 3205 DCA REC1
00217 1205 TAD REC1
00220 3212 DCA REC2
00221 1205 TAD REC1 /COPY 1000 OS/8 BLOCKS
00222 1231 TAD KM2000 /WHICH IS 2000 TAPE BLOCKS
00223 7710 SPA CLA
00224 5202 JMP LOOP /KEEP COPYING
00225 7240 CLA CMA /7777 TO AC
00226 7402 HLT
00227 5226 JMP .-1 /PROTECTION
00230 0036 K36, 36
00231 6000 KM2000,-2000
00232 7200 K7200, 7200
00233 7204 K7204, 7204
$$$$$$

```


This program uses the subroutine at 7200 to read the tape on unit 0 and copy 1000 OS/8 records to unit 1. The program terminates normally with 7777 in the AC. Any other value in the AC indicates a tape error has occurred. Restart at 0200 to try the copy again.

This procedure can be used to make as many copies as needed. After copying, the master tape should be stored safely, and a copy tape should be initialized.

II) TD8E Initialization Program

Once the master tape is backed up, a copy tape should be initialized to a TD8E configuration. Instructions to do this can be found in the OS/8 Users Guide. The initialization program consists of two parts:

- A) The RIM format paper tape supplied with the OS/8 kits.
- B) Records 2-6 of the OS/8 system tape contain the actual initializer program. This is put onto every system tape delivered from the Library.

The RIM format tape reads in blocks 2-6 and starts execution. The program in blocks 2-6 contains all code needed to transform the tape. Users should also be aware of the following information about the initializer:

- A) Blocks 2-6 are OS/8 directory records. If the directory is expanded enough to move into block 2, the initializer program is destroyed. That is why the initializer program should be run immediately after copying the system tape.
- B) PIP using the /Y option does not copy blocks 2-6 to the output tape. Thus, a tape that passes through the /Y option should never be used with the initializer. This will be corrected in a future version of PIP.
- C) The initializer can be used repeatedly, until block 2 is used for directory functions. This should not be necessary, however, and is not recommended.

III) Write Locked System Device

The initializer will print random characters on the TTY if the system tape is WRITE LOCKED during initialization. This is due to an erroneous indirect operation in the initializer. The typeout should be:

```
DEVICE ERROR
```

and the system should halt. If typeout occurs, halt the machine WRITE ENABLE the drive, and start the RIM format initializer again at either location 20 (8K-ROM) or 21 (12K).

PDP-8/12 RTPS FORTRAN IV

Programming note, formatted end of file

The run-time handling of end of file for formatted files is designed so that if end of file is encountered during program execution, the program continues at the start of the file, rather than generating a fatal error. The next release of FORTRAN may include a library function to check for end of file at the users option.

PDP-8/12 RTPS FORTRAN IV

Programming Note, constants in call list

As specified in the ANSI standard, constants in call lists of subroutines and function subprograms are not protected.

Therefore, a function such as the following will result in erroneous values.

```
FUNCTION FNCL(Y)
```

```
FNCL = 100.0
```

```
Y = Y+2.0
```

```
RETURN
```

```
END
```


Arithmetic statement function definitions

The arguments of an RTPS FORTRAN IV arithmetic statement function definition are not dummy arguments.

RTPS FORTRAN IV users should note section 11.1.1 of the FORTRAN manual which concerns dummy arguments in arithmetic statement function definitions. It should read as follows:

Form: name (arg1,....) = expression

Where: arg1,.. are arguments. These variables will be altered whenever the function is used and should not be used elsewhere in the program.

Effect: defines an internal function.

RTPS FORTRAN IV (F4.SV version 1.06, RALF.SV version 51)

The BLOCK DATA statement

The BLOCK DATA statement does not function properly.

However, the BLOCK DATA subprogram is not required by RTPS FORTRAN IV. Data statements associated with variables in COMMON may appear in the main program or any subprogram.

RTPS FORTRAN IV (F4.SV version 1.06, RALF.SV version 51)

The BLOCK DATA statement

The BLOCK DATA statement does not function properly.

However, the BLOCK DATA subprogram is not required by RTPS FORTRAN IV. Data statements associated with variables in COMMON may appear in the main program or any subprogram.

PDP-8/12 RTPS FORTRAN IV

Problem with expression in I/O statement

In an I/O statement (READ, WRITE, DEFINE FILE), an expression should not be used in the rightmost field. Thus,

```
READ (4'NXT-2)M
```

is not stored properly by the compiler, but

```
READ (4'SEC)M
```

is acceptable. This problem will be corrected in the next release of the compiler.

RTPS FORTRAN IV (F4SV version 1.06)

Problem with logical expressions

When an arithmetic expression is on the right-hand side of a logical expression, and the logical condition is greater than (.GT.), greater than or equal to (.GE.), less than (.LT.), or less than or equal to (.LE.), the zero condition will not be properly checked. Specifically, .GT. and .LT. do check for zero, but, .GE. and .LE. do not.

This problem will be corrected in the next release of the FORTRAN system. The problem can be easily avoided by calculating the arithmetic expression first and then using it in the logical expression. Thus,

```
J=K-1  
IF (L.GT.J) GO TO 10
```

will work correctly, but

```
IF (L.GT.K-1) GO TO 10
```

will not.

FOCAL 8

Patch to correct Altmode location

The following patch allows 376 to be accepted as Altmode instead of 375. The ASCII code 375 will no longer be valid if this patch is made:

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>
7002	0375	0376

For these teletypes which have only an ESCape key ASCII code 0233 may be inserted as follows:

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>
7002	0375	0233

FOCAL-8 and FOCAL '69

Problem with M Command

A problem occurs in both versions of FOCAL when the M command is used to modify lines with line numbers that end in .63.

To avoid problems when modifying any line numbered xx.63, the entire line should be deleted using the ERASE command and re-entered.

TC58 IT PART 1 (MAINDEC-08-D9DE)

Patch to correct short stall loops

Because of the increased cycle time of the PDP-8/E, the current stall loops of TC58 IT Part 1 may be marginally too short. To correct this, change the following locations to increase this particular stall.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>
3262	5253	5340
3340		2337
3341		5340
3342		5253

PDP-8/12 NEW AND REVISED SOFTWARE

KE-8E (EAE) Instruction Test 2 Multiply and Divide

MAINDEC-8E-DØMA

There have been three problems diagnosed in this program.

1. The binary tape does not entirely match the listing.
2. The teletype reader will not read a tape for interrupt testing.
3. Halts defined in the document must be changed to conform to binary tape.

The corrections for these problems are as follows:

1. A new MAINDEC will be released at a later date.
2. To start the TTY reader, press any key on the teletype keyboard.
3. Change the following halts defined in the document:

Paragraph 5.1.1.

Ø2Ø1 to Ø2ØØ
Ø251 to Ø25Ø

