DECUS
PROGRAM LIBRARY

DECUS NO.	84
TITLE	M.I.T. Floating Point Arithmetic Package
AUTHOR	Bill Gasper and Tom Eggers
COMPANY	Massachusetts Institute of Technology
DATE	
FORMAT	

M.I.T. FLOATING POINT ARITHMETIC PACKAGE

Program Library Write-up DECUS No. 84

The Floating Package is a group of arithmetic subroutines in which numbers are represented in the form $f \times 2^e$. f is a one's complement 18-bit fraction with the binary point between bits 0 and 1. e is a one's complement 18-bit integer exponent of 2. The largest magnitude numbers that can be represented are $\sim 10^{39,000}$.

A number is normalized when $\frac{1}{2} \leq |f| < 1$. All the floating routines, except the two floating unnormalized adds, return a normalized answer. The fraction appears in the ac, the exponent in the io. Description of routines:

Floating Add - jda fad

One argument should appear in the ac-io. The other argument should have the addresses, direct or indirect, of the fraction and exponent in the two registers following the jda fad.

```
lca f1          /load first argument
lio e1
jda fad         /call floating add
  f2            /address of second fraction
  e2            /address of exponent for second
                   fraction
dac             /control returns to here with
                /normalized answer in ac-io
```

Floating Multiply - jda fmp

```
lac f1          /Load multiplicand.
lio e1
jda fmp         /Call floating multiply
  f2            /address of fraction of multiplier
  e2            /address of exponent of multiplier
dac             /Control returns to here with normal-
                /ized answer in ac-io.
```

Floating Divide - jda fdv

```
lac f1          /Load first argument.
lio e1
jda fdv         /Call divide.
  f2            /address for divisor, hlt will occur
  e2               /if f2=0.
dac             /Control returns here with normalized
                /answer in ac-io.
```

Floating Square Root - jda fsq

Execution time ~385 μsec.

```
        lac f           /Load argument; argument must be
                            normalized
        lio e
        jda fsq         /Call square root; hlt will occur
                        /unless f ≥ 0.
        dac             /Control returns here with normalized
                        /answer in ac-io.
```

Floating Log, base 2 - jda log

```
        lac f           /Load argument.
        lio e
        jda log         /Call log; hlt will occur unless f > 0.
        dac             /Control returns here with normalized
                        /answer in ac-io.
```

Floating Reciprocal - jda rcp

```
        lac f           /Load argument.
        lio e
        jda rcp         /Call reciprocal; hlt will occur in
                        /fdh if f=0.
        dac             /Control returns here with normalized
                        /answer in ac-io.
```

Floating Input - jda fip

```
        jda fip         /Call input; ac-io don't matter.
        jsp             /This instruction is repeatedly
                        /executed (xct) in order to get the
                        /input characters.  The jsp (or jda)
                        /could call a typewriter or reader
                        /listen loop subroutine which should
                        /return the input characters in the
                        /low bits of the io.
        dac             /Control returns here with the answer
                        /in the ac-io after the first illegal
                        /character.
```

Legal characters for fip

x resets routine and starts forming a new number. Spaces and code deleted characters are ignored. Legal characters are: ., e, 0-9, -, x, and space. The illegal character that terminated the number is in register fip.

Input examples:

```
6.9el
690 e-1234
-6.9 e 17
```

Floating Output - jda fop

```
lac f                   /Load argument.
lio e
jda fop                 /Call output.
tyo                     /an executed instruction (xct) for
                        /output
dac                     /Control returns here with normalized
                        /floating point input quantity.
```

The routine generates parity for each character, so the executed output instruction could be a ppa or a call to an output subroutine.

The output format is .71000 e2, 5 significant figures.

Floating Unnormalized Add - jda fua

```
lac fl                  /Load first argument.
lio el
jda fua                 /Call unnormalized add.
  f2                    /addresses of second argument
  e2
```

The subroutine returns with a 35 bit number in the ac-io with binary point after the bit number equal to the larger exponent of the two arguments. If the addition produces an overflow, the larger exponent is incremented by 1. In any case, the larger exponent, perhaps incremented, appears in fac+1. Examples for subroutine:

```
lac  (200000            /½
lio  (0
jda  fua
  (0                    /zero with exponent to cause the number
  (17.                  /to be fixed.
```

At return ac,io equals 0,400000.

```
lac (0                  /0
lio (16.
jda fua
  (200000               /½
  (0
```

At return ac,io equals 1,0.

Floating Unnormalized Add and Round - jda fur

```
lac fl              /Load argument
lio el
jda fur             /Call unnormalized add and round
  f2                /addresses of second argument
  e2
dac                 /Control returns here with fraction
                    /in ac and exponent in io.
```

This routine is the same as fad except that the answer is not normalized. The larger exponent returns in the io, unless overflow occured. Then the larger exponent +1 returns in the io. Example:

```
lac (300000         /3
lio (2
jda fur             /Call subroutine.
  (0                /zero with exponent to
  (17.              /cause the answer to be fixed.
```

At return, ac,io equals 3,17.

Floating Exponentiation - jda f2x

This subroutine calculates 2^x. Execution time $\sim$ 1.3 m sec.

```
lac f               /Load argument.
lio e
jda f2x             /Call subroutine.
dac                 /Control returns to here with normalized
                    /answer in ac-io.
```

```
/floating pack with trig func, arctan, and nat log

fac,    0           0

fmp,    0           /floating multiply
        dap fm1
        dap fm2
        idx fm2
        dap frx
        idx frx
        swp
fm2,    add i .
        dac fac 1
fm1,    lac i .
        mul fmp
        dac fac
        jmp fnm
```

```
fnm,    cla         /normalize.  For internal use only
        dap fnr
        add fac
        sza 1
        jmp fze
flp,    sub (200000
        sma
        jmp fnr
        idx fnr
        lac fac
        scl 1
fdf,    dac fac
        jmp flp
fze,    law 17.
        dap fnr
        lac fac
        scl 9s
        scl 8s
        add (0
        sza
        jmp fdf
fnr,    law 1 .
        add fac 1
        dac fac 1

frn,    lac fac     /round.        "
        sar 9s
        sar 8s
        clo
        scl 1
        add fac
        lio fac 1
        szo 1
frx,    jmp .
        rar 1
        swp
        idx fac 1
        swp
        jmp frx
```

```
fdv,    0           /floating divide
        dap fd1
        dap fd2
        idx fd2
        dap frx
        idx frx
        swp
fd2,    sub i .
        dac fac 1
        lac fdv
        cli
        spa
        lio (-0
fd1,    div i .
        jmp fdo
        dac fac
        cla
        spi
        cma
        swp
        div i fd1
        hlt         /impossible
        scr 9s
        scr 8s      /or mul (1
        jmp fnm
fdo,    add (0
        sza i
        hlt         /zero divisor
        scr 1
        dac fdv
        idx fac 1
        lac fdv
        jmp fd1
```

```
fad,    0           /floating add
        dap fa1
        dap fa2
        idx fa2
        dap frx
        idx frx
        law fnm
        dap fux
        cla
        add i fa1
        sza
        jmp fnz
        lac fad
fzn,    dac fac
        dio fac 1
        cli
        spa
        lio (-0
        jmp fnm
fnz,    cla
        add fad
        sza
        jmp fah
        lac i fa1
        lio i fa2
        jmp fzn
fah,    dac fua
        jmp fun
```

```
fua,    0           /unnormalized floating add (fix)
        dap fa1
        dap fa2
        idx fa2
        dap fux
        idx fux
fun,    swp
        dac fac 1
fa2,    sub i .
        sma
        jmp fsr
        dac fde
        lac i fa2
        dac fac 1
        lac fua
        dac fa4
fa1,    lac i .
        dac fua
fba,    cli
        spa
        lio (-0
        dio fa4 1
        scr 1
        and (377777
        dac fmp
        swp
        sar 1
        and (377777
        dac fad
        lac fde
        scr 3s
        add (5
        spq
        jmp fou
        add .+1
        dap fsh
        clc
        scl 3s
        add (fsp 7
        dap fxq
        lac fa4
        cli
        spa
        lio (-0
fsh,    jmp .
        repeat 4, scr 8s
fxq,    xct .
        and (377777
        swp
        sar 1
        and (377777
        add fad
        dac fa3 1
        spa
```

```
            idx fmp
            swp
            cma
            sub fmp
            cma
            dac fa3
            sma
            jmp ful
            law i 1
            sub fa3 1
            cma
            dac fa3 1
            sas (400000
            jmp ful
            law i 1
            sub fa3
            cma
            dac fa3
ful,        lac fa3
            lio fa3 1
            ril 1
            rcl 1
            scr 2s
            scl 2s
            dac fac
            xor fa4
            dac fa3
            lac fac
            xor fua
            and fa3
            sma
            jmp fok
            idx fac 1
            lac fac
            scr 1
            xor (400000
            dac fac
fok,        lac fac
            dio fa4 1
fux,        jmp .

fsr,        cma
            dac fde
            lac i fa1
            dac fa4
            lac fua
            jmp fba
fou,        lac fua
            lio fa4 1
            jmp fok-1
fa3,        0           0         fa4,        0           0
fs8=0
fsp,        repeat 8., scr 8s-fs8             fs8=fs8 fs8 1
fde,        0
```

```
fur,      0          /unnormalized rounded add
          dap fu1
          dap fu2
          idx fu2
          dap frx
          idx frx
          lac fur
          jda fua
fu1,      i .
fu2,      i .
          jmp frn

/square root   jda fsq   Inputs must be normalized (or 0)
fsq,      0
          dap zlv
          law i 3    dac zlv 1
          spi
          cma
          rcr 1
          dio zlv 2
          xor zlv 2
          swp
          spi sma-skp
          idx zlv 2
          lac fsq
          spa
          hlt
          sza i
          jmp zlv-1
          spi
          sar 1
          dac fsq
          sar 2s
          add zlv 3
          jmp . 11
          lac fsq
          cli
          scr 2s
          dis zlv 4
          hlt
          add zlv 4
          cli
          rcr 1
          dac zlv 4
          isp zlv 1
          jmp .-12
          lac zlv 4
          scl 1
          sza i
          sub (400000
          lio zlv 2
zlv,      jmp
          0          0
          66314      0
```

```
/log, base 2.  requires normalized arg

log,    0
        dap lgo
        dio lgo 6
        lac log
        spq
        hlt
        sar 1
        add lgo 1
        dac lg
        lac log
        sub lgo 2
        cli
        spa
        lio (-0
        div lg
        hlt             /not norm.
        dac lg          mul lg
        mul lgo 3
        sar 4s
        add lgo 4
        mul lg
        sub lgo 5
        lio (1
        jda fad
        lgo 6           (17.
lgo,    jmp .
        132405      265012      373621
        270517      100002      0
lg,     0
```

```
/floating input: jda fip, input inst
fip,    0
        dap owt     dap wat   idx owt
ini,    dzm hol
        dzm hol 1
        dzm zl1
        dzm dig
        lio wat 3   /spa
        dio cns
        dio cnn
        dio 6fg
wat,    xct .
        dio fip
        rcr 7s
        spa
        jmp wat
        sar 2s
        sar 9s
        lio fns 2   /sma
        sad (charac rx
        jmp ini
        sza i
        jmp wat
        sas (charac r-
        jmp 5fg
        dio cns
        jmp wat
5fg,    sas (charac r.
        jmp . 3
        dio cnn
        jmp wat
        sas (charac re
        jmp cnm
        dio 6fg
        lio wat 3
        dio cns
        jmp wat
cnm,    sad har 1
        cla
        sub wah
        sma
        jmp fns
        add wah
cns,    spa .
        cma
        dac zl2
        cla
6fg,    spa .
        jmp cxp
cnn,    spa .
        idx dig
        lac hol
        lio hol 1
        jda fmp
        wah
        har 5
        jda fad
        zl2
        har 5
        dac hol
        dio hol 1
        jmp wat
```

```
cxp,    lac zl1
        sal 2s
        add zl1
        sal 1s
        add zl2
        dac zl1
        jmp wat
fns,    lac zl1
        sub dig
        sma
        lio . 1
        spa
        cma
        dac zl1
        dio cpr
cpr,    spa .-.
        jsp inv
        law har
        dap tnp
        law har 1
        dap tnp 1
rpt,    lac zl1
        sza i
        jmp ard 4
        scr 1
        dac zl1
        spi i
        jmp ard
        lac hol
        lio hol 1
        jda fmp
        tnp i
        tnp 1 i
        dac hol
        dio hol 1
ard,    idx tnp 1
        dap tnp
        idx tnp 1
        jmp rpt
        xct cpr
        jsp inv
        lac hol
        lio hol 1
owt,    jmp .
inv,    dap qzl
        lac hol
        sza i
        jmp owt-1
        lio hol 1
        jda rcp
        dac hol
        dio hol 1
qzl,    jmp .-.
wah,    10.
zl1,    0          zl2,    0
```

```
/floating output

fop,        0
            dap urp
            dap xit
            idx xit
            law har 30.
            dap tnp
            law har 31.
            dap tnp 1
            cla
            dap ubm
            lac fop
            dio 151
            lio 2hn
            sma
            jmp urp
            cma
            dac fop
            lio (charac r-
urp,        xct .-.
            lac fop
            lio 151
            jda fmp
            (5
            har 5
            dzm loh
            sza i spi-skp
            jmp mzd
            jda rcp
            dac fop
            rcr 9s
            rcr 9s
            sub (1
            dac 151
            law spa-skp sma-skp
            dap ubm
mzd,        dzm dig
            lac fop
            lio 151
            dac lst
            dio lst 1
            jda fdv
tnp,        har 30.
            har 31.
            dac fop
            dio 151
            jda fmp
            (5
            har 5       spi
            jmp tuf
            idx dig
            jmp mzd 1
tuf,        lac lst
            lio lst 1
```

```
            dac fop
            dio 151
            lac loh
2hn,        sal 200
            add dig
            dac loh
            law i 2
            add tnp
            dap tnp
            dap tnp 1
            idx tnp 1
            sas tob
            jmp mzd
ubm,        skp .-.
            jmp drp
            lac c1
            lio c1 1
            jda fdv
            fop
            151
            dac fop
            dio 151
drp,        lio (charac r.
            xct urp
            lac fop
            lio 151
            jda fmp
            tn5
            har
            jda fur
            (0
            har 5
            jda dpt
            xct urp
            lio 2hn
            xct urp
            lio (265
            xct urp
            lac loh
            cma
            xct ubm
            cma
            jda dpt
            xct urp
xit,        jmp .-.
har,        20.         20          100.        17.         10000.
17.
97656.      27.         72759.      54.         80778.      107.
99565.      213.        75632.      426.        87283.      851.
116246.     1701.       103097.     3402.       81093.      6804.
100343.     13607.      76818.      27214.      90042.      54427.
123712.     108853.
tob,        har-1       loh,        0
hol,        0           0
lst,        0           0
c1,         314632      -3
dig,        0           151,        0           tn5,        12500.
```

```
/decimal integer print of ac.  jda dpt followed by output instr.

dpt,      0
          dap dpo
          dap dpx
          dzm ddv
          idx dpx
          lio (charac r-
dlp,      lac dpt
          spa
          xct dpo
          spa
          cma
          dac dpt
dl1,      dac dpr
          mul (1
          div (10.
dpr,      0
          sas ddv
          jmp dl1
          sni                    /note sni
          lio (charac r0
dpo,      xct .
          lac dpr
          dac ddv
          sas dpt
          jmp dlp
dpx,      jmp .
ddv,      0

/parity for low 6 io bits, saves ac
pty,      0
          dap ytp
          law i 770
          rcr 6s
          lio (252002
          rcr 9s
          dap . 1
          rir
          spi
          and pty 2
          rcl 6s
          rcl 9s
          lac pty
ytp,      jmp .

/reciprocal routine
rcp,      0
          dap pcr
          dio pcr 1
          cli
          law 1200
          rcl 9s
          jda fdv
          rcp
          pcr 1
pcr,      jmp .
pcr 1,    0
```

```
/antilog, base 2
f2x,      0
          dap fxx
          lac f2x
          dio f2x
          lio (nop
          spa
          lio (jda rcp
          dio fck
          spa
          cma
          lio f2x
          jda fua
          (0
          (17.
          dac fmp
          idx fmp
          law 17.
          sas fac 1
          hlt          /power too big
          lac (200000
          dac fac
          law ftb
          dap fmt
fci,      spi i
          jmp fz0
          dio z11
fmt,      lac .
          mul fac
          scl 1
          dac fac
          spi
          idx fac
          lio z11
fz0,      idx fmt
          sad (lac ftb 16.
          jmp fdu
          rcl 1
          sni i
          jmp fci
fdu,      lac fac
          lio fmp
fck,      .-. .
fxx,      jmp .
ftb,      265017    230160    213454    205526    202633
201312    200544    200262    200131    200054    200026
200013    200006    200003    200001    200001
```

```
/x to the y power
pow,        0
            dap po1
            dap po2
            idx po2
            dap pox
            idx pox
            lac pow
            jda log
            jda fmp
po1,        i .
po2,        i .
            jda f2x
pox,        jmp .
```

```
/floating normal angle,  for internal use only

fna,        0
            dap rt1
            clf 6
            dio fed
            lac fna
            spa
            jmp inc
            lac fna
            lio fed
            jda fad
            (-311040
            (3
            sma
            dac fna
            sma
            dio fed
            sma
            jmp .-12
            lac fna
            lio fed
            jda fad
            (-226630
            (3
            sma
            jmp 4q
            jda fad
            (311040
            (1
            sma
            jmp 3q
            jda fad
            (311040
            (1
            sma
            jmp 2q
            lac fna
            lio fed
rt1,        jmp .
inc,        lac fna
            jda fad
            (311040
            (3
            dac fna
            dio fed
            jmp fna 4
4q,         dac fna
            dio fed
            stf 6
            lac fna

            lio fed
2q,         cma
            jda fad
            (311040
            (1
            dac fna
            dio fed
            jmp rt1-2
3q,         dac fna

            dio fed
```

```
            stf 6
            jmp rt1-2

/floating sin-cos

fcs,        0
            dap rt2
            lac fcs
            jda fad
            (311040
            (1
            jda fna
            dac fsn
            dio fex
            jmp .+5
fsn,        0
            dap rt2
            lac fsn
            jda fna
            dac fsn
            dio fex
            jda fmp
            fsn
            fex
            dac fxs
            dio fes
            jda fmp
            fsn
            fex
            jda fmp
            (252533
            (-2
            dac fdd
            dio fed
            cma
            jda fad
            fsn
            fex
            dac fcs
            dio fee
            lac fdd
            lio fed
            jda fmp
            fxs
            fes
            jda fmp
            (314637
            (-4
            dac fdd
            dio fed
            jda fad
            fcs
            fee
            dac fcs
            dio fee
            lac fdd
            lio fed
            jda fmp
            (303034
            (-5
```

```
            cma
            jda fad
            fcs
            fee
            sza i
            lio fex


            sza i
            lac fsn
            szf 6
            cma
rt2,        jmp .

/floating secant - cosecant

fsc,        0
            dap rt3
            lac fsc
            jda fad
            (311040
            (1
            dac fco
            jmp .+3
fco,        0
            dap rt3
            lac fco
            jda fsn
            sza i
            jmp .+3
            jda rcp
rt3,        jmp .
            lio (377777         lai
            jmp rt3
```

```
/floating tan cot

ftn,    0
        dap rt4
        dio fte
        lac ftn
        jda fcs
        dac fsc
        sza i
        jmp rt4 1
        dio fco
        lac ftn
        lio fte
        jda fsn
        jda fdv
        fsc
        fco
rt4,    jmp .
        lio (377777
        lai
        jmp rt4

fct,    0
        dap rt5
        dio fte
        lac fct
        jda fsn
        dac fsc
        sza i
        jmp rt5 1
        dio fco
        lac fct
        lio fte
        jda fcs
        jda fdv
        fsc
        fco
rt5,    jmp .
        lio (377777
        lai
        jmp rt5
```

```
fln,    0           /floating natural log
        dap rt6
        dio eln
        lac fln
        spq
        hlt
        lac (200000
        dac lnc
        lac (1
        dac lce
        lac fln
        jda fad
        lnc
        lce
        dac fln
        dio eln
        jda fad
        (-200000
        (2
        jda fdv
        fln
        eln
        dac fln
        dio eln
        dac lna
        dio lne
        jda fmp
        fln
        eln
        dac fls
        dio els
lrp,    lac lnc
        lio lce
        jda fad
        (200000
        (2
        dac lnc
        dio lce
        lac fln
        lio eln
        jda fmp
        fls
        els
        jda fdv
        lnc
        lce
        jda fad
        lna
        lne
        sad lna
        jmp rt6 1
        dac lna
        dio lne
rt6,    jmp .
        jda fmp     (200000
        (2
        jmp rt6
```

```
atn,    0
        dap atx
        lac atn
        dac att
        dio att 1
        sma
        cma
        jda fad
        (200000
        (1
        sma
        jmp at5
        lac att
        lio att 1
        jda rcp
        dac att
        dio att 1
        law at4
        skp i
at5,    law at 1
        dap at
        lac att
        lio att 1
        jda fmp
        att
        att 1
        dac btt
        dio btt 1
        law gt
        dap at1
        law gt1
        dap at1 1
        lac att
        lio att 1
        jda fmp
        ht
        ht 1
        dac ctt
        dio ctt 1
```

```
at2,    lac att
        lio att 1
        jda fmp
        btt
        btt 1
        dac att
        dio att 1
        jda fmp
at1,    .
        .
        jda fad
        ctt
        ctt 1
        dac ctt
        dio ctt 1
        idx at1
        idx at1 1
        sas (gt1 4
        jmp at2
at,     jmp .
        lac ctt
atx,    jmp .

at4,    lio ctt
        lac (311040
        spi 1
        cma
        lio (1
        jda fad
        ctt
        ctt 1
        cma                     /   pi/2 - arccot(x)
        jmp atx

att,    0           0
btt,    0           0
ctt,    0           0
ht,     377772      0
gt,     -251072     270355    -256271     252535
gt1,    -1          -2        -3          -5


variables
constants
start
```